MI 3123 SMARTEC Earth / Clamp

Professional solution for smart operator





Main Features:

- Supports all types of earthing resistance measurements:
 - Standard earthing resistance measurement with spikes
 - Selective earthing resistance test with one current clamp
 - Selective (contact less) earthing resistance with two current clamps
 - Specific earth resistance measurement
- Leakage current tests with current clamps
- Load current tests with current clamps
- High accuracy, high immunity against external noise
- Preprogrammed limits
- PASS/FAIL evaluation of measurement result
- Bright GREEN/RED indicators provides visual evaluation of results
- Suited for testing on CAT IV installations
- Magnetic holder enables hands-free operation
- Built-in battery charger
- Two level memory structure for saving test results and parameters
- Basic downloading with EuroLink PRO PC SW package
- Compatible with EuroLink PRO Plus PC SW package
- USB and RS232 ports
- Robust and ergonomic design



Two clamps method for testing ground resistance of object on TN system



Large LCD screen with backlight and PASS/FAIL indicators

Suitable for:

- Testing earthing resistance
- Testing main earthing of objects
- Testing resistance of individual earthing rods in large systems
- Testing lightning systems
- Determination of soil resistivity
- Designing of earthing systems
- Testing on CAT IV installations (outside installations, main distribution boards, industrial plants)

Standards:

Instrument: IEC/EN 61557 Parts 1,5,10 IEC/EN 61010-1 IEC/EN 61326

Applications: IEC/EN 60364 VDE 100 BS 7671 17th edition CEI 64.8



Technical specifications

Earth resistance

Earth resistance 4-wire method and Earth resistance one clamp method Measuring range according to EN61557 is 0.67 Ω ÷ 9999 Ω

Measuring range R (Ω)	Resolution (Ω)	Accuracy
0.00 ÷ 19.99	0.01	±(3 % of reading + 3 digits)
20.0 ÷ 199.9	0.1	±(3 % of reading + 3 digits)
200 ÷ 1999	1	± 5 % of reading
2000 ÷ 9999	1	± 10 % of reading

Automatic test of probe resistance ves Automatic test of voltage noise ves Open-terminal test voltage 40 VAC Test voltage frequency 125 Hz Short-circuit test current < 20 mA Low clamp current indication yes Noise current indication yes

Earth resistance two clamps method

	Measuring range (Ω)	Resolution (Ω)	Accuracy
	0.00 ÷ 19.9	0.01	± (10 % of reading + 10 digits)
	20.0 ÷ 30.0	0.1	± (20 % of reading)
	30.1 ÷ 39.9	0.1	±(30 % of reading)
_	· · · · · · ·	105.11	

Test voltage frequency 125 Hz Noise current indication ves Low clamp current indication ves

Specific earth resistance

Measuring range (Ωm)	Resolution (Ωm)	Accuracy
0.0 ÷ 99.9	0.1	Calculated value, consider earth resistance 4-wire method
100 ÷ 999	1	
1.00k ÷ 9.99k	0.01k	
10.0k ÷ 99.9k	0.1k	
>100k	1k	

Wenner method principle with equal distances between test probes: ρ = $2\cdot\pi\cdot\text{distance}\cdot\text{R},$ with R as measured resistance in 4-wire method.

TRMS Clamp current

Measuring range ()	Resolution (mA)	Accuracy
0.0 mA ÷ 99.9 mA	0.1mA	±(3 % of reading + 3 digits)
100 mA ÷ 999 mA	1 mA	±(3 % of reading + 3 digits)
1.00 A÷ 19.99 A	0.01 A	±(3 % of reading + 3 digits)

Maximum input current 30 mA (=30 A @ current clamp with ratio 1000:1)

Measurement principle current clamp, ratio 1000:1

40 Hz ÷ 500 Hz Nominal frequency

General data

Power supply voltage 6 x 1.5 V battery or rechargeable battery, size AA

Operation Overvoltage category 50 V CAT IV Protection classification double insulation

Pollution degree Protection degree

128 x 64 dots matrix display with backlight Display Communication transfer speed 115200 baud (RS 232) / 256000 baud (USB)

Memmory 1900 measurements

Dimensions (w x h x d) 14 cm x 8 cm x 23 cm Weight without battery cells 0,85 kg

Measuring and Regulation Equipment Manufacturer

METREL d.d. Ljubljanska 77

SI-1354 Horjul Tel: + 386 (0)1 75 58 200 Fax: + 386 (0)1 75 49 226 E-mail: metrel@metrel.si http://www.metrel.si

Ordering information

MI 3123 Standard set



Instrument MI 3123 Earth / Clamp

Soft hand strap

Earth test lead 4,5 m (blue) Earth test lead 4,5 m (red) Earth test lead 20 m (green)

Earth test lead 20 m (black) Earth test rod, 4 pcs

Power supply adapter + 6 NiMH rechargeable AA batteries

Instruction manual on CD Short instruction manual Product verification data

Handbook "Guide for testing and verification of low

voltage installations" on CD

Optional Accessories

Photo	Order No.	Decription
	A 1018	Current clamp (low range, leakage)
3	A 1019	Current clamp
	A 1160	Fast battery charger with a set of 6 pcs NiMH rechargeable AA batteries
	A 1271	Small soft carrying bag
	A 1289	Soft carrying bag
Manua	A 1290	PC SW EuroLink PRO Plus with USB and RS232/PS2 cable
MI INI	A 1291	PC SW EuroLink PRO with USB and RS232/ PS2 cable
ANS S	S 2041	Earth test set 50 m
A	S 2009	Test lead set 2 m, 4 colours, 4 pcs

Note! Photographs in this catalogue may slightly differ from the instruments at the time of delivery. Subject to technical change without notice.